





# FEET OF CLAY

Using SG54 Feet Sprig Mold



Work with the same clay to make the feet as was used to make the project. Push the moist clay into the selected cavity of the mold. Using a plastic or rubber scraper, remove the excess clay. Use a small piece of clay to help lift the foot from the mold cavity.



Score both joining surfaces and use compatible slip to add the feet to the vessel. It can be helpful to use a board or piece of glass to level the feet while the feet are moist. While the piece is inverted you may elect to add decorative elements to the bottom of the piece



After the clay has been allowed to set up, upturn the footed vessel and add decorative elements to the top of the piece if desired. Place the entire piece in a bag and allow it to dry gradually and completely before firing.



SG54 Feet Sprig Mold can produce 9 varieties of feet, ranging in size from .75" dia. – 1.5" dia.